










Register Print

Site Name (Main Building 001X / 10501993)

Building	Floor	Location	Item	Material	Project No.	Sample No	Size	Identification	Condition	Location	Vulnerability	Covering	Action Code	Orig. ID	
	0	090 RESOURCES	Above Ceiling	Bitumen Product	H-03431	17769-2	S2	Asbestos Not Detected						711533	
<i>Residues to roof deck</i>															
	0	090 RESOURCES	Above Ceiling	Asbestos Not Detected	H-03431	ND								711534	
<i>Beneath insulation to pipework</i>															
	0	090 RESOURCES	Above Ceiling	Asbestos Not Detected	H-03431	ND								2647945	
<i>Firebreak</i>															
	0	090 RESOURCES	Above Ceiling	Asbestos Not Detected	H-03431	ND								2647954	
<i>Extractor ducting</i>															
	0	090 RESOURCES	Above Ceiling – Other Surfaces	Asbestos Not Detected	H-03431	ND								2647932	
	0	090 RESOURCES	Extractor	Asbestos Not Detected	H-03431	ND								2647953	
<i>Ceiling mounted</i>															
	0	090 RESOURCES	Skylights	Putty	H-03431	Y*	H-03431-03	S1	Chrysotile	Good condition - including painted installations and those in original condition	Low Occupancy Areas	Disturbance Unlikely - installation can not normally be reached	None	Low Priority (P4)	900212
<i>Sealant to wired glazing</i>															
	0	090 RESOURCES	Under Carpet/Lino	Asbestos Not Detected	H-03431	ND								711535	
	0	090 RESOURCES	Other Surfaces	Asbestos Not Detected	H-03431	ND								711536	