

HCC WINCHESTER DISTRICT : TRAFFIC MANAGEMENT PROGRAMME 2010/2011 - CORE SERVICE - TABLE 3a

updated - 16 September 2010

TRAFFIC MANAGEMENT REQUESTS, INVESTIGATIONS AND PROJECTS

REF	PARISH	LOCATION	ISSUE	NOTES	CTY MEM	OFCR	PROGRESS
758	ALRESFORD	Spring Gardens	TRO for Road Closure	Western end of Spring Gardens goes through a ford at the river Itchen. Ford is not suitable for normal cars. HHW have had a road closed sign up for a while which has deferred cars but tractors still able to go through. Needs official road closure by order - possibly physical.			Highways are obtaining the Parish Council view and will fund any closure measures.
660	BISHOPS SUTTON	village	signing	(i) report of missing bridge headroom sign - between 'secundus' and railway bridge. (ii) report of junction sign where no junction - between Mill Lane and Western Court.	Hindson		
752	BORDON	Woodside Close	bar marking review	request for H bar outside 16 Woodside Close	Carew		
579	DENMEAD	Closewood Rd / Hambledon Rd	speed limit review	request to include cluster of properties in Closewood Road in speed limit, plus developer request extend 30mph on Hambledon Road.	Allgood	IJ	Police agree to reduction of 40mph to 30mph between Waterlooville and Denmead and the extension in to Closewood Rd - supported by Member. Proposals advertised and approved. Implementation date being agreed with S278 engineer to link with MDA works.
730	DENMEAD	Soake Road	driver awareness of bends	Request for warning signs and road marking improvements.	Allgood	MCW	MP involvement. Proposals to be prepared for warning signs and SLOW markings.
393	EASTON	Fair Lane	traffic speed concerns	Concern about speed of traffic there as Winchester Garden Machinery business grows. Combined with 583.	Porter		

604	HEADBOURNE WORTHY	Church Green Close (private)	speed limit sign review	Provision of 30mph terminal signs within 20m of junction to ensure enforcement of village 30.	Porter		
678	HINTON AMPNER	A272 around Hinton Arms	Sign amendments	Parish Council request sign changes to village nameplates of neighbouring parishes and tourist signs.	Hindson		Advice provided. Hinton Ampner Parish Council to liaise with Bramdean over position of Village nameplates.
629	KINGS WORTHY	Lovedon Lane and Park Lane	sign reflectivity	requires night time inspection, sign reflectivity low which gives misleading view in the dark, consider whether sign illumination is necessary for safety reasons. Accident history exists at Lovedon Lane, Park Lane and A33 junction.	Porter	SW	
741	NEW ALRESFORD	A31 Park Lodge	U-turning	TM advice on measures such as a gap closure to reduce u-turning.	Porter	CP	CP provided advice on gap closure. Highways Winchester to take forward.
742	OLD ALRESFORD	Village	30mph speed limit order	Amendment of 2008 Village 30 order. Side road needs inclusion in consolidation order and the extension of the 30mph on The Broadway to Abbotstone Lane to include the brook.	Porter		
594b	SPEED LIMIT REMINDER SIGN		parish owned SLR applications	Review sites and applications put forward by Parish Councils for parish owned speed limit reminder signs either singularly or as cluster group.	all	CP	Ongoing delivery
555	WICKHAM	A334 / A32	speed limit terminal signing	Signs need lighting : A334 - 30/40 north of coldharbour close, and A32 30/50 south of A334 roundabout.	Allgood	CP	Street lighting engineers provided with details and job number to arrange works.
677	WINCHESTER	College Street	inappropriate use by large vehicles	Reported - large vehicles (coaches, lorries) entering Kingsgate Street get stuck at the junction of College Street, at Winchester College, and hitting no 15 College Street. Problems are caused by those who do not need to use the route. This route is used by pupils of the College.	Collin	WCC	WCC have designed a scheme for a kerbed build-out and bollard, but are awaiting HCC funding. EF being explored.
583	WINCHESTER	B3404, Alresford Road (Fair Lane to A31 roundabout, including Fair Lane)	speed review and signing	SPEED LIMIT - traffic speed concerns in the vicinity of the Intech site will also be included in county wide A and B road review. There is the Percy Hobbs caravan park and mobile home park near by which accommodates walkers and tourists. SIGNING - signing for Intech directs traffic around the roundabout, but roundabout not visible from sign, drivers are confused and use the Intech junction area instead of proceeding to the roundabout, the hotel is under construction and will require direction signing, through audit ensure that the new signing does not exacerbate the existing situation. Councillor priority HIGH.	Porter		
751	WINCHESTER	Petersfield Road	speed limit sign review	lack of derestriction repeater signs in a street lit section at Percy Hobbs roundabout.	Porter		

COMPLETE TRAFFIC MANAGEMENT REQUESTS, INVESTIGATIONS AND PROJECTS

REF	PARISH	LOCATION	ISSUE	NOTES	CTY MEM	OFCR	PROGRESS
29	BISHOPS WALTHAM	Beeches Hill	traffic speed and volume	CAPITAL PROGRAMME : long term trial traffic calming (chicanes) ongoing.	mason	MCW	Exec Member decision to approve on 30 Apr 09. Works being arranged by HHE. Start date 6 April 2010, revised to 12 April and then 4 May. WORKS NOW COMPLETE.
667	SHEDFIELD	Clewers Hill	traffic issues	HGV traffic use - restrictions exist, request for further restriction.	Hindson	RO	NO FURTHER ACTION
448	TICHBORNE	Ladycroft	traffic issues / awareness / speed limit signing	speed limit signing to be reviewed as repeaters missing, also ped in rd signing and road markings agreed at mtg	Porter	RH	Proposals developed and completed. Further amendments agreed with Parish Council and ordered. WORKS NOW COMPLETE.