

Addendum to Agenda Item 8 of the Meeting of the River Hamble Harbour Board on Friday 25 September 2015

- 3.39. 15 Sep. Patrol assisted a large ketch in berthing in adverse weather conditions.
- 3.40. 19 Sep. Patrol towed a broken-down RIB to the fuelling jetty.
- 3.41. 20 Sep. Patrol stood by a small motor craft aground on Hamble Spit pending he refloating. Towed a yacht to Warsash Slipway with a fouled propeller. Stood by another yacht with engine difficulties on passage upriver to Deacon's Boatyard.
- 3.42. 21 Sep. Patrol investigated a report of speeding RIBs in the vicinity of Universal Marina. Two RIBs located and reminded of the River Speed Limit of 6 Knots and the requirement to minimise wash.
- 3.43. 23 Sep. Patrol towed a yacht with a propulsion defect from the fuel berth to Mercury Yacht Harbour.
- 3.44. 24 Sep. Patrol to Manor Farm to inspect jetty condition.